

P 032250Z JUL 67

FM NPIC WASHDC

TO RUCSAAA/SAC OFFUTT AFB OMAHA NEB

RUCVAAA/4080 STRAT WG OL 19 BARKSDALE AFB LA

RUCVAAA/2D RTS BARKSDALE AFB LA

RUEPJS/DIA WASHDC

RUCIJRA/NAVRECONTECHSUPPCEN SUITLAND MD

RUEPIA/CIA WASHDC

RUWBKNA/15TH AF MARCH AFB RIVERSIDE CALIF

RUCVAAA/2 AF BARKSDALE AFB LA

BT

037 JUL 3 23 12Z

OUT62484

S E C R E T CITE NPIC 1144.

15TH AF (FOR DI), SAC (GLASS LAMP, DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B-24 WAS USED ON MISSION G964 FLOWN ON 1 JULY 1967.

PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. DENSITY AND RESOLUTION ARE GOOD WHERE NOT DEGRADED BY ATMOSPHERIC CONDITIONS.

B. 9R SIDE: NUMEROUS FINE EMULSION SCRATHES ALONG THE MAJOR AXIS OF THE FILM ARE PRESENT ON FRAME 518. MINOR FOGGING CAUSED BY NON-IMAGE FORMING LIGHT IS PRESENT ON FRAMES 601/602 AND 630.

C. 9L SIDE: PLUS DENSITY AREAS ASSOCIATED WITH ROLLER CHATTER ARE PRESENT ALONG THE INBOARD EDGE THROUGHOUT THE MISSION. VERY FINE EMULSION SCRATHES ARE PRESENT ALONG THE MAJOR AXIS OF THE FILM THROUGHOUT. EMULSION LIFTS AND GOUGES ARE PRESENT INTERMITTENTLY. EXAMPLE: FRAMES 363, 370, 379 AND 383.

D. BOTH SIDES: EDGE FOG CAUSED BY STATIC IS PRESENT ALONG THE OUTBOARD EDGES THROUGHOUT. THE LAST TITLED FRAME IS 972. MODE FIVE OF CAMERA OPERATION WAS UTILIZED THROUGHOUT. CYCLE RATE IS 4.5 SECONDS WITH APPROXIMATELY 60 PERCENT OVERLAP BETWEEN VERTICAL FRAMES.

3. POSITIVE:

DISTRIBUTION 2		
Cx No.	Office	Action
1	File	
2	OS	
	SEC BR	
	TDS	
	CSD	
	IPD	
	FD	
	ESD	
	EDICB	
345	TID	
	IAD	
	PAG	
	PAAX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

Advance copy  
Submitted

Declass Review by NGA

SECRET



--2--

- A. PI SUITABILITY IS GOOD WHERE NOT DEGRADED BY ATMOSPHERICS.
- B. PRINTING AND PROCESSING ARE GOOD.
- C. CLOUD COVER OBSCURED APPROXIMATELY 70 PERCENT OF THE

MISSION.

GP-1

S E C R E T

END OF MESSAGE